

Instrucciones de montaje
Installation Instructions
Notice d'installation
Istruzioni per il montaggio
Montageanweisung
Montagehandleiding






Montagevejledning
Οδηγίες εγκατάστασης
Instruções de montagem
Monteringsanvisning
Asennusohje
Návod k montáži

Paigaldusjuhend
Szerelési utasítás
Montāžas instrukcija
Montavimo instrukcija
Instrukcja montażu
Navodila za montažo






Návod na montáž
Монтажни инструкции
Instrucţiuni de montaj
Инструкция по монтажу
安装说明


IEC/EN62208 AC≤1000V DC≤1500V

IEC/EN60670-1-24 AC/DC≤400V





		A (mm)	B (mm)	C (mm)
GME14PO	(1 x 14M)	337	302	-
GME14PO/PH			-	304
GME28PO	(2 x 14M)	502	467	-
GME28PO/PH			-	469
GME42PO	(3 x 14M)	627	592	-
GME42PO/PH			-	594
GME56PO	(4 x 14M)	752	717	-
GME56PO/PH			-	719
GME70PO	(5 x 14M)	877	842	-
GME70PO/PH			-	844


											
GME14PO	1	1	1	1	2	-	1	/PH x4	10	1	
GME28PO										2	
GME42PO						1	-			3	
GME56PO								/PH x6		4	
GME70PO										5	



GMExxPO/xx/RR (In<125A)	N (mm ²)	PE (mm ²)
GME14PO/xx/RR	6x(2.5-6mm ²)+6x(4-10mm ²)+1x(10-25mm ²)+1x(16-35mm ²)	6x(2.5-6mm ²)+6x(4-10mm ²)+1x(10-25mm ²)+1x(16-35mm ²)
GME28PO/xx/RR	8x(2.5-6mm ²)+8x(4-10mm ²)+1x(10-25mm ²)+1x(16-35mm ²)	8x(2.5-6mm ²)+8x(4-10mm ²)+1x(10-25mm ²)+1x(16-35mm ²)
GME42PO/xx/RR	16x(2.5-6mm ²)+16x(4-10mm ²)+2x(10-25mm ²)+2x(16-35mm ²)	16x(2.5-6mm ²)+16x(4-10mm ²)+2x(10-25mm ²)+2x(16-35mm ²)
GME56PO/xx/RR	16x(2.5-6mm ²)+16x(4-10mm ²)+2x(10-25mm ²)+2x(16-35mm ²)	16x(2.5-6mm ²)+16x(4-10mm ²)+2x(10-25mm ²)+2x(16-35mm ²)
GME70PO/xx/RR	[12x(2.5-6mm ²)+12x(4-10mm ²)+1x(10-25mm ²)+1x(16-35mm ²)] x 2	[12x(2.5-6mm ²)+12x(4-10mm ²)+1x(10-25mm ²)+1x(16-35mm ²)] x 2
GMExxPO/xx/RA (In<125A)	N (mm ²)	PE (mm ²)
GME14PO/xx/RA	2x(25mm ²)+14x(4mm ²)	2x(25mm ²)+14x(4mm ²)
GME28PO/xx/RA	3x(25mm ²)+14x(4mm ²)	3x(25mm ²)+14x(4mm ²)
GME42PO/xx/RA	4x(25mm ²)+28x(4mm ²)	4x(25mm ²)+28x(4mm ²)
GME56PO/xx/RA	5x(25mm ²)+28x(4mm ²)	5x(25mm ²)+28x(4mm ²)
GME70PO/xx/RA	[4x(25mm ²)+28x(4mm ²)] x 2	[4x(25mm ²)+28x(4mm ²)] x 2



GMExxPO/PH



GMExxPO

